



AIC Inc.

No. 9, Alley 19, Lane20

Da Hsing Rd. Luchu Township, Taoyuan, Taiwan

TEL: +886-3-3138386

FAX: +886-3-3138377

4U60 Single Expander (XJ3000-4603) SSG JBOD Functionality Report

DOC No. : FM131128A3-X4JS6000

| | | |
|--|--|---|
| Initiated by DQA 2013.11.28 Jack Huang | Reviewed by DQA 2013.11.28 Chuan Lee | Approved by VP, Quality 2013.11.28 David Yu |
| Originate Date | Revision | Report Status |
| 2013/11/28 | A3 | MP |

Copyright©2013 AIC Inc. This document contains information proprietary to AIC Company .
Use or disclosure without written permission of an officer of AIC expressly forbidden.

Revision History

Revisions

| REV. | DESCRIPTION | DATE | Engineer |
|------|---|------------|------------|
| A0 | XJ3000-4603 JBOD Functionality Test for DVT | 2012/5/4 | Jack Huang |
| A1 | <p>XJ3000-4603 Basic Functionality Test- PSU Substitute</p> <p>ECN: XJ3000-4603 JBOD Functionality Test Expander: B46-LISAXXE-00C110(Reworked) Hub F/W: 1.11.2.4 MFG: 1.2.0.3 Left Edge F/W: 1.11.3.3 MFG: 1.3.0.2 Right Edge F/W: 1.11.3.3 MFG: 1.3.1.2</p> <p>Solution: 1. <u>Resolve the issue that the zone behavior was not proper with Adaptec raid card.</u> Solution: 2. <u>Changed bead of expander board, let signal was improved.</u></p> | 2013/4/16 | Jack Huang |
| A2 | <p>ECN: XJ3000-4603 JBOD Functionality Test Expander: B46-LISAXXE-00C210(Reworked) Configuration1: Hub F/W: 2A2_v1.11.2.4; MFG: mfg2A2.0_4U60_Hub_A020_1105; Left Edge F/W: fw2A3_v1.11.3.3; MFG: mfg2A3.0_4U60_LeftEdge_A020_1105; Right Edge F/W: fw2A3_v1.11.3.3; MFG: mfg2A3.1_4U60_RightEdge_A020_1105 Solution: <u>Tune signal while deployed the 600mm mini-SAS cable to use.</u></p> <p>Configuration2: Hub F/W: fw2A2_v1.11.2.4; MFG: mfg2A2.0_4U60_Hub_C210_1105; Left Edge F/W: fw2A3_v1.11.3.3; MFG: mfg2A3.0_4U60_LeftEdge_C210_1105; Right Edge F/W: fw2A3_v1.11.3.3; MFG: mfg2A3.1_4U60_RightEdge_C210_1105 Solution: <u>Tune signal while deployed the 180mm mini-SAS cable to use.</u></p> | 2013/11/21 | Jack Huang |

If product change or information change/update, the report will be revised and released next edition.

Copyright©2013 AIC Inc. This document contains information proprietary to AIC Company .
 Use or disclosure without written permission of an officer of AIC expressly forbidden.



AIC Inc.

REV A3
 Page 2 of 15

| Revisions | | | |
|---|--|------------|------------|
| REV. | DESCRIPTION | DATE | Engineer |
| A3 | XJ3000-4603 Basic Functionality Test ECN: XJ3000-4603 JBOD Functionality Test Hub F/W: 01.11.02.52 MFG: 1.2.0.51 Left Edge F/W: 01.11.03.52 MFG: 1.3.0.51 Right Edge F/W: 01.11.03.52 MFG: 1.3.1.51 Solution: 1. <u>F/W and MFG upgraded. Hidden Right/left edge expander, let physical drivies plug under hub expander.</u> Solution: 2. <u>Enable T10 zoning function.</u> | 2013/11/28 | Jack Huang |
| If product change or information change/update, the report will be revised and released next edition. | | | |

| Date of Test: | |
|---------------|----------------|
| Test Started | Test Completed |
| 2013/11/25 | 2013/11/28 |

Copyright©2013 AIC Inc. This document contains information proprietary to AIC Company .
Use or disclosure without written permission of an officer of AIC expressly forbidden.

| | | |
|-----|----------|------------------------|
| AIC | AIC Inc. | REV A3 Page 3 of 15 |
|-----|----------|------------------------|

Table of Contents

| | |
|--|----|
| 1 Introduction..... | 5 |
| 1.1 Scope..... | 5 |
| 1.2 Purpose..... | 5 |
| 1.3 Reference Information..... | 5 |
| 2 Plan of Action Reference..... | 6 |
| 2.1 Plan of Action Procedure..... | 6 |
| 2.2 Test Reporting..... | 6 |
| 3 DUT Images..... | 7 |
| 4 Target Device Configuration and Environment..... | 8 |
| 4.1 Table of Test Configuration..... | 8 |
| 4.2 Main Hardware Configuration..... | 8 |
| 5 Functional Test..... | 9 |
| 6 RAID Card Test..... | 13 |
| 7 HBA Card Test..... | 14 |
| 8 Summary..... | 15 |

Copyright©2013 AIC Inc. This document contains information proprietary to AIC Company .
Use or disclosure without written permission of an officer of AIC expressly forbidden.

1 Introduction

1.1 Scope

This document is for demonstrating product conformance in the Various Development Phases of a project.

1.2 Purpose

Provide a formal and consistent process for measuring and validation the reliability of a given design. Identify any design discrepancies or electrical, mechanical, firmware and system issues.

1.3 Reference Information

The following documents form a part of this test plan to the extent specified herein.

- DVT Requirements Document
- Current Hardware Platform Evaluation Test Plan

| Owner | Document List Review |
|-------|---|
| PM | Application form for DVT functionality validation |
| PM | Product specification |
| EE1 | Product EVT test report |
| QT | Board level compatibility EVT test report |
| EE1 | PCB Schematic / Layout |

2 Plan of Action Reference

2.1 Plan of Action Procedure

- Refer to this document or other identified specification to start product testing.
- Identify all necessary requirements and equipment for the test.
 - All equipment must be calibrated on an annual basis. Documentation of the calibration must be available.
 - Proper maintenance of equipment is required.
- Complete testing according to instructions or procedures contained in this document.
- Identify whether or not product or product component passes or fails.
- Report all test results to DQA designated personnel and database.
 - Within the Problem Tracking System, the function test shall be referenced in the short description of the issue.
- The EE design teams have the responsibility to resolve all issues and concerns by PVT date.
- Identified issues and concerns will be worked in order of priority and resolved according to the mechanical checklist and any associated documented specifications.
- The QAE team may identify resolution for an issue regarding a product in the design process, if it is deemed necessary for the QAE team to be involved.

2.2 Test Reporting


Throughout the process of development, all progress in testing must be tracked and communicated to the DQA weekly.

Each test shall be tracked as follows:

| Definition | Description |
|------------|---|
| Pass | All units were able to complete testing within the specified Pass Criteria. |
| Fail | UUT were not able to complete testing within the specified Fail Criteria |
| Bug | Unable to predict potential problems |
| Pending | Test initially failed but is able to pass after fixes were implemented |

All Pass/Fail data results must be repeatable.

3 DUT Images



Front Angle



Top Open Angle



Rear Angle

4 Target Device Configuration and Environment

4.1 Table of Test Configuration

| Host Configuration | | | | | |
|---|----------------|-------------------|--------------------|--------------------------|-------------------|
| Item | | Vender / Model | | Detail | |
| Mortherbord | | Intel S2600CP | | Motherboard of the host | |
| Operation System1 | | Microsoft Windows | | Server 2008 R2 64-bit | |
| Operation System2 | | CentOS6.3 | | 2.6.32-279.el6.x86_64 | |
| CPU | | Intel | | E5-2643 3.30GHz *1 | |
| Memory | | DSL | | DDR3 1066 U-DIMM/ 2GB *6 | |
| Hard Disk Drive | | WD / WD3000HLFS | | SATA HDD / 300GB *1 | |
| PCIe Card Configuration | | | | | |
| Card | Vender / Model | Firmware ver. | BIOS ver. | Driver ver. | GUI Software ver. |
| RAID Card | Intel RS2PI008 | 2.130.383-2315 | 3.27.00_4.12.05.00 | 6.600.23.0 | 13.04.03.01 |
| HBA Card | LSI 9206-16E | 17.00.01.00 | 7.33.00.00 | 2.0.66.0 | 13.08.04.01 |
| XJ3000-4603 Single JBOD HDD Configuration | | | | | |
| Vender / Model | | Interface | | Detail | |
| Seagate / ST3146855SS | | SAS 3G | | 146GB/ FW: 0002 | |
| Seagate / HUS723030ALS640 | | SAS 6G | | 3TB/ FW: A222 | |
| Toshiba / AL13SEL900 | | SAS 6G | | 900GB/ FW: 6101 | |
| Hitachi / HUA723030ALA640 | | SATA 6G | | 3TB/ FW: 800 | |

4.2 Main Hardware Configuration

| Item | Product Number | Quantity | Detail |
|----------------|--|----------|---|
| Backplane | B40-4AMPTMXX00A010 B40-4AMMTMXX00B010 (Reworked as B40-4AMPTMXX00A110, B40-4AMMTMXX00B110) | 2 | SN: 421-12060801010002 SN: 421-12060801020008 |
| Power Housing | Zippy M1X4-7AH9V0H | 1 | AC INPUT: 100-240V 47-63Hz 33-16.5A / DC OUTPUT : 1890W(MAX) |
| Power Module | Zippy M1X-3700V | 4 | AC INPUT: 100-240V 47-63Hz 11-5.5A DC OUTPUT: 700W(MAX) |
| Expander board | B46-LISAXXE-00C110 (Reworked as B46-LISAXXE-00C210) | 1 | SN: 505-12031400310037 SASAddress: 50015B219800553F 50015B219800563F 50015B219800543F |
| Fan Module | SANYO DENKI SAN ACE 80 | 4 | DC 12V/3.8A |
| Mini-SAS cable | Innovative and Advance Technology Co., Ltd RMS36-1194 REV AX1 | 15 | SFF-8087 to SFF-8087 600mm |

5 Functional Test

| | | | |
|--|---|--|------------------------|
| Test Engineer | | Jack Huang | |
| Model Name | | XJ3000-4603 | |
| Firmware | | Hub: LSISAS2xFW-01.11.02.52 / Edge: LSISAS2xFW-01.11.03.52 | |
| MFG | | Hub: 1.2.0.51 Left Edge: 1.3.0.51 Right Edge:1.3.1.51 | |
| Expander Board | | B46-LISAXXE-00C110(Reworked as B46-LISAXXE-00C210) | |
| Backplane | | B40-4AMMTMXX00B010, B40-4AMPTMXX00A010(Reworked as B40-4AMPTMXX00A110, B40-4AMMTMXX00B110) | |
| RAID Card | | Intel RAID RS2PI008 | Driver6.600.23.0 |
| Power Housing | | Zippy M1X4-7AH9V0H | |
| Power Module | | Zippy M1X-3700V | |
| Item Test | Power Module | | |
| Test Procedure | | | Result |
| Hot swap the power module and power cord, confirm the right side of functions are work normally. | Hot-swap each PSU 10 times under power on state, check fail led, buzz and console status. | | Pass |
| | Power cord interrupt, check fail led, buzz, console status. | | Pass |
| | PSU status under GUI. | | Pass |
| | PSU status under console. | | Pass |
| | | | |
| Item Test | System Fan | | |
| Test Procedure | | | Result |
| Hot swap or start/ stop the fan module, and confirm the right side of functions are work normally. | Hot-swap fan module under power on state, check fail led, GUI, buzz and console status. | | Pass |
| | If fan speed was changed, the fan status could also been change under GUI. | | Pass |
| | Fan status under console. | | Pass |
| | Smart fan, if temperature upgrade, the rotational speed of fan was increased. | | Pass |
| | Hot-swap each fan module 10 times, the system was not generate any abnormal message. | | Pass |
| AIC | AIC Inc. | | REV A3 Page 9 of 15 |

| | | |
|--|---|-------------------------|
| | | |
| Item Test | LED Color of Front Panel | |
| Test Procedure | | Result |
| Check LED color of front panel. | Power Fail LED | Blue/Red |
| | Temperature Alarm LED | Blue/Red |
| | Fan Alarm LED | Blue/Red |
| | HDD Access LED | Blue/Red |
| | | |
| Item Test | Voltage Sensor | |
| Test Procedure | | Result |
| To check if value of the voltage from the specific function showing the status is ok. | Check voltage under Hyperterminal status. | Pass |
| | Check voltage under GUI | Pass |
| | | |
| Item Test | HDD Interface | |
| Test Procedure | | Result |
| Insert HDD into disk bays, then hot swap some HDD, and check all access LED, and RS-232 console status is normal. HDD could be SAS/SATA interface. The right side of list are the HDD interface. | SAS HDD | Pass |
| | SATA HDD | Pass |
| | | |
| Item Test | Power Cycle | |
| Test Procedure | | Result |
| Execute power cycle to verify if JBOD boot and shutdown repeatedly, the system still runs normally. | Power cycle this device 15 times, check the expander could be detected, and no error message was be occurred. | Pass |
| | | |
| AIC | AIC Inc. | REV A3 Page 10 of 15 |

| | | |
|---|---|-------------------------|
| | | |
| Item Test | SAS Zoning | |
| Test Procedure | | Result |
| Applying SAS Zoning function to segment HDD group. | Take HDD to build zonecount1, and run Iometer under this HDD group configuration. | Pass |
| | Take HDD to build zonecount4, and run Iometer under this HDD group configuration. | Pass |
| | Take HDD to build zonecount2, and run Iometer under this HDD group configuration. | Pass |
| | | |
| Item Test | Expander | |
| Test Procedure | | Result |
| Check channel of expander that function is ok. | Check phy state and negotiated link speed, confirm the phy contents conform with actual HDD configuration | Pass |
| | | |
| Item Test | SES Lighting Signal | |
| Test Procedure | | Result |
| To verify SES lighting signal, using sg3_utils tool to check lighting mode of each status is correct. | Request consistency check in progress | Pass |
| | Request in critical array | Pass |
| | Request in failed array | Pass |
| | Request rebuild/ remap | Pass |
| | Request rebuild/ remap aborted | Pass |
| | Request device missing indication | Pass |
| | Request insert | Pass |
| | Request removal | Pass |
| | Request identify | Pass |
| | Request fault indication | Pass |
| | | |
| AIC | AIC Inc. | REV A3 Page 11 of 15 |

| | | |
|--|---|-------------------------|
| | | |
| Item Test | Temperature Sensor | |
| Test Procedure | | Result |
| When temperature sensor \geq designated degree, the GUI will spring up warning message, and fan speed from the RS232 console showing the status is normal. | T1, T2, warning, Alarm value configuration setting | Pass |
| | Temperature detected status under GUI | Pass |
| | Temperature detected status under Hyperterminal | Pass |
| | Break through T1 value, the rotational speed of fan was increased | Pass |
| | Break through alarm value, then the fail led will light up | Pass |
| | Break through alarm value, beep from buzzer | Pass |
| | Break through alarm value, RPM of fan is the highest | Pass |
| | | |
| Item Test | Firmware Upgrade | |
| Test Procedure | | Result |
| To upgrade the firmware then check if upgrade successfully. | In band mode(debug port) | Pass |
| | Out-of-band mode(console port) | Pass |
| | | |
| Item Test | Burn-in Test | |
| Test Procedure | | Result |
| Using performance assessment tool, let JBOD status was maintain full loading on 12 hours. | Adjust conf. to 100% read | Pass |
| | Adjust conf. to 100% write | Pass |
| | | |
| Item Test | Power Saving | |
| Test Procedure | | Result |
| Check power saving function is ok. | Key in "sas_standby_timer" command under console, then waiting a little time, check current was diminished. | Pass |
| | | |
| AIC | AIC Inc. | REV A3 Page 12 of 15 |

6 RAID Card Test

| | | | |
|----------------|--|--------|------------|
| Test Engineer | Jack Huang | | |
| Model Name | XJ3000-4603 | | |
| Firmware | Hub: LSISAS2xFW-01.11.02.52 / Edge: LSISAS2xFW-01.11.03.52 | | |
| MFG | Hub: 1.2.0.51 Left Edge: 1.3.0.51 Right Edge: 1.3.1.51 | | |
| Expander Board | B46-LISAXXE-00C110(Reworked as B46-LISAXXE-00C210) | | |
| Backplane | B40-4AMMTMXX00B010, B40-4AMPTMXX00A010(Reworked as B40-4AMPTMXX00A110, B40-4AMMTMXX00B110) | | |
| RAID Card | Intel RAID RS2PI008 | Driver | 6.600.23.0 |
| Power Housing | Zippy M1X4-7AH9V0H | | |
| Power Module | Zippy M1X-3700V | | |

| RAID Function | Test Procedure | Result |
|---------------------------------|--|--------|
| Intel RS2PI008 RAID Function | Create/Remove a RAID 0 volume | Pass |
| | Create/Rebuild/Remove a RAID 1 volume | Pass |
| | Create/Rebuild/Remove a RAID 5 volume | Pass |
| | Create/Rebuild/Remove a RAID 6 volume | Pass |
| | Create/Rebuild/Remove a RAID 10 volume | Pass |
| | Create/Rebuild/Remove a RAID 50 volume | Pass |
| | Remove a crashed RAID 0 volume | Pass |
| | Remove a crashed RAID 1 volume | Pass |
| | Remove a crashed RAID 5 volume | Pass |
| | Remove a crashed RAID 6 volume | Pass |
| | Remove a crashed RAID 10 volume | Pass |
| | Remove a crashed RAID 50 volume | Pass |

Note: 1. There are some strange information under RAID card's BIOS.

7 HBA Card Test

| | | | |
|----------------|--|--------|----------|
| Test Engineer | Jack Huang | | |
| Model Name | XJ3000-4603 | | |
| Firmware | Hub: LSI SAS2xFW-01.11.02.52 / Edge: LSI SAS2xFW-01.11.03.52 | | |
| MFG | Hub: 1.2.0.51 Left Edge: 1.3.0.51 Right Edge: 1.3.1.51 | | |
| Expander Board | B46-LISAXXE-00C110(Reworked as B46-LISAXXE-00C210) | | |
| Backplane | B40-4AMMTMXX00B010, B40-4AMPTMXX00A010(Reworked as B40-4AMPTMXX00A110, B40-4AMMTMXX00B110) | | |
| RAID Card | LSI 9206-16E | Driver | 2.0.66.0 |
| Power Housing | Zippy M1X4-7AH9V0H | | |
| Power Module | Zippy M1X-3700V | | |

| HBA Function | Test Procedure | Result |
|-----------------------|---|--------|
| LSI 9206-16E HBA Card | While using LSI 9206-16E HBA to connect with XJ3000-4603 Single Expander SAS JBOD. Then check if all hard drives can be detect by LSI BIOS utility. | Pass |
| | While using LSI 9206-16E HBA to connect with XJ3000-4603 Single Expander SAS JBOD. Then check if all hard drives can be detect by GUI. | Pass |
| | While using LSI 9206-16E HBA to connect with XJ3000-4603 Single Expander SAS JBOD. Then check if all hard drives can be detect by OS Disk management. | Pass |

Note: 1. While using LSI 9206-16E HBA card to locate LED of the slot, it did not respond.

8 Summary

| Item | Descriptions | Result |
|-------------------------|--------------------------|--------|
| Enclosure Function Test | Power Module | Pass |
| | System Fan | Pass |
| | LED Color of Front Panel | Pass |
| | Voltage Sensor | Pass |
| | HDD Interface | Pass |
| | Power Cycle | Pass |
| | SAS Zoning | Pass |
| | Expander | Pass |
| | SES Lighting Signal | Pass |
| | Temperature Sensor | Pass |
| | Firmware Upgrade | Pass |
| | Burn-in Test | Pass |
| | Power Saving | Pass |
| RAID Card Test | Intel RS2PI008 | Pass |
| HBA Card Test | LSI 9206-16e | Pass |

**** Notes:** Test items and test contents depend on spec.

Bug List

Class

| | |
|---|-------------------|
| A | Major |
| B | Minor |
| C | Limitation |
| D | Other(Suggestion) |

| NO. | Date | Class | Bug/Limitation/Suggestion | Initiator | Status | Solution |
|-----|------------|-------|--|-----------|--------|--|
| 1 | 2013/11/26 | C | Using LSI 9206-16E HBA Card couldn,t locate LED. But Adaptec 7085H could locate LED. | Jack | Close | It is known limitation while hidden right/left expander. |
| 2 | 2013/11/26 | C | While using Intel RS2PI008 RAID card, there are some strange information under BIOS. ex.Device##: Unknow etc... | Jack | Close | It is known limitation while hidden right/left expander. |