Release Note for AIC SAS 6G 4U60 Hub Expander

Jul 1, 2014


Changelog


07/01/2014 (firmware 1.11.2.5 + mfg 1.2.0.4) - Part Number (B98-004U60E2110205 + B98-004JS6G2020004) Old Part Number B98-004JS6G2020003 is replaced by B98-004JS6G2020004. 1. Resolve the drive mapping issue in Windows with SAS 12G HBA
 11/14/2013 (firmware 1.11.2.5 + mfg 1.2.0.3) - Part Number (B98-004U60E2110205 + B98-004JS6G2020003) Old Part Number B98-004U60E2110204 is replaced by B98-004U60E2110205. 1. Add the console command "serial_number" to configure Expander serial number and Enclosure serial number. 2. Add the console command "enclosure addr" to configure the enclosure address.
02/26/2013 (firmware 1.11.2.4 + mfg 1.2.0.3) - Part Number (B98-004U60E2110204 + B98-004JS6G2020003) Old Part Number B98-004U60E2110203 is replaced by B98-004U60E2110204. 1. Resolve the compatibility issue when zone count is 2 or 4
10/25/2012 (firmware 1.11.2.3 + mfg 1.2.0.3) - Part Number (B98-004U60E2110203 + B98-004JS6G2020003) Old Part Number B98-004U60E2110202 is replaced by B98-004U60E2110203. Old Part Number B98-004JS6E2020002 is replaced by B98-004JS6G2020003. 1. Resolve the fan speed level issue
04/24/2012 (firmware 1.11.2.2 + mfg 1.2.0.2 + firmware 1.11.3.2 + mfg 1.3.0.2 + mfg 1.3.1.2) 1. Remove the section "Supported Topology", and add two sections, "Supported Configuration" and "Unsupported Configuration"
03/12/2012 (firmware 1.11.2.2 + mfg 1.2.0.2 + firmware 1.11.3.2 + mfg 1.3.0.2 + mfg 1.3.1.2) 1. Add the enclosure identity
03/09/2012 (firmware 1.11.2.1 + mfg 1.2.0.2 + firmware 1.11.3.2 + mfg 1.3.0.2 + mfg 1.3.1.2) 1. Improve signal for SATA drive
02/15/2012 (firmware 1.11.2.1 + mfg 1.2.0.1 + firmware 1.11.3.1 + mfg 1.3.0.1 + mfg 1.3.1.1) 1. Initial revision

Definition of the visual LED indicators (blue and red) associated with a disk drive

Host Control Bit Bi	lue LED	Red LED
OKOfRSVD DEVICEOfHOT SPAREOfCONS CHECKOfIN FAILED ARRAYOfIN FAILED ARRAYOfREBUILD/REMAPOfR/R ABORTOfACTIVEOfDO NOT REMOVEOfINSERTOfINSERTOfIDENTSIFAULTOfDEVICE OFFOf	N N N N N N N N N N N N N N N N N N	OFF OFF Fast blink Slow blink Slow blink Fast blink Slow blink OFF ON Slow blink Slow blink OFF ON Slow blink

Supported Configuration





Unsupported Configuration

1. This only applies to the enclosure which supports dual AIC 6G Expander Controllers. The enclosure with dual AIC 6G Expander Controllers attached is inserted with a SATA drive without any interposer. It will cause the drive LEDs behaves incorrect.

Command Line Interface Operation

1. How to configure zone count

Remove the SAS cable between the HBA/RAID card and the 4U60 before configuring zone count. Power off the 4U60 after configuring zone count. Power on the 4U60, then insert the SAS cable.

Three zone configurations supported are one zone with 60 drives, two zones with 30 drives per zone, and four zones with 15 drives per zone. The default configuration is one zone of which T10 zoning configuration is disabled. T10 zoning configuration of the other configurations (two zones and four zones) is enabled.

Each of three COM ports (COM for Hub, COM for Left Edge, and COM for Right Edge) should be applied with the same zone configuration.

- (A) Check the current zone configuration cmd> zonecount Zone count = 1
- (B) One-zone configuration to support one host and up to three down links. The host can access up to 60 drives in this 4U60. cmd> zonecount 1 cmd> reset
- (C) Two-zone configuration to support two hosts and up to one down link per host. Each host can access up to 30 drives in this 4U60. cmd> zonecount 2 cmd> reset
- (D) Four-zone configuration to support four hosts. Each host can access up to 15 drives in this 4U60. cmd> zonecount 4 cmd> reset
- How to get all revisions in AIC SAS 6G Expander (A) Expander firmware revision cmd> rev
 - (B) Expander configuration revision

cmd> showmfg

- (C) Microchip firmware for managing sensors (Only the COM for Hub supports this command) cmd> sensor
- 3. How to configure temperature sensor
 - Four temperature settings in Celsius are T1, T2, warning threshold, and alarm (critical) threshold. Only the COM for Hub supports this command.
 - (A) Get the current temperature settings cmd> temperature Temperature in Celsius (t1=20 C, t2=55 C, warning=50 C, alarm=55 C)
 - (B) Set temperature with new T1=18 C, T2=52 C, warning threshold=48 C, and alarm threshold=54 C. The new setting will take effect after reset. cmd> temperature 18 52 48 54 cmd> reset

4. How to identify the enclosure

The LED on the power button is used for the enclosure identity. The "RQST IDENT" for Enclosure is defined in the bytel and bit7 of the "Enclosure control element" in the SES-3 specification. Please install a software package "sg_utils" on your host computer, and have a SAS HBA and a cable to connect your host with the expander. We use Linux for example.

(A) Show the device for the enclosure
 \$ sg_map -i

/dev/sg60 AIC CORP 4U60: Hub 0b02 /dev/sg64 AIC CORP 4U60: Left Edge 0b03 /dev/sg65 AIC CORP 4U60: Right Edge 0b03

- (B) Enable the enclosure identity (Only Hub should be applied) \$ sg_ses --descriptor=EnclosureElement01 --set=1:7:1 /dev/sg60
- (C) Disable the enclosure identity (Only Hub should be applied) \$ sg_ses --descriptor=EnclosureElement01 --clear=1:7:1 /dev/sg60

5. How to configure enclosure address

- (A) Get the current enclosure address cmd> enclosure_addr Enclosure Address: 0x500605B0000272BF
- (B) Set the enclosure address with 0x500605B0000272BF. The new setting will take effect after reset. cmd> enclosure_addr 500605B0000272BF cmd> reset
- 6. How to configure serial number
 - (A) Get the current serial number cmd> serial_number Expander number: 421-12021704510010 or Expander number: 421-12021704510010 Enclosure number: 526-12071100500088
 - (B) Only set Expander serial number with 421-12021704510010. cmd> serial_number 421-12021704510010
 - (C) Set both of Expander serial number (421-12021704510010) and Enclosure serial number (526-12071100500088). cmd> serial_number 421-12021704510010 526-12071100500088